



Connecting Tecopa: Bicycle and Pedestrian Safety Corridor Barriers, Improvements and New Routes/Facilities



Connecting Tecopa: Bicycle and Pedestrian Safety Corridor Tecopa Hot Springs - Barriers, Improvements and New Routes/Facilities



Barriers to Mobility:

- 1, Bike lanes end south of Tecopa Hot Springs. No bike/ped facilities in community center
- 2, Unsigned existing crosswalk provides inadequate safety for pedestrians
- 3, Inadequate separation from high-speed vehicles (55+ mph)
- 4, Short sight distance at Triangle, conflict with vehicles on roadway, no pedestrian crossings
- 5, No bike/ped facilities in community center
- 6, Conflict between bikes/peds and vehicles on roadway

Connecting Tecopa: Bicycle and Pedestrian Safety Corridor Tecopa Hot Springs - Barriers, Improvements and New Routes/Facilities



Barriers to Mobility:

- 1, Bike lanes end south of Tecopa Hot Springs. No bike/ped facilities in community center
- 2, Unsigned existing crosswalk provides inadequate safety for pedestrians
- 3, Inadequate separation from high-speed vehicles (55+ mph)
- 4, Short sight distance at Triangle, conflict with vehicles on roadway, no pedestrian crossings
- 5, No bike/ped facilities in community center
- 6, Conflict between bikes/peds and vehicles on roadway